

# ROYAL<sup>®</sup> aawas

---

Jorhat | by Royal Group

*Construction Update*  
*March 2025*



March 2025



Block A1

RERA KM 15 OF 2022-2023

### Structural Work

- Foundation Work Completed
- Ground to 8<sup>th</sup> Floor Roof Slab Casted
- Lift Machine Room, Pergola, Head Room & Overhead Water Tank Casted

### Masonry Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor AAC Block Masonry Work Completed

### Plastering Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Internal Plaster Completed
- Outside Plastering Work Completed

### Electrical Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Electrical Pipe Concealed Work Completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Wiring & Switch sockets fitting completed

### Carpentry Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Flush Door fitting work completed

### Plumbing Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom Wall & Kitchen Pipe Concealed Work Completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom & Kitchen 4" Pipe Line Completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom & Kitchen CP Sanitary fittings work Completed

### Waterproof Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Completed

### Putty & Paint Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor inside and outside putty Work completed
- A1 Tower External Paint Work completed

### Tiles Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor tiles & Kitchen slab granite fitting Work completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom floors and wall tiles & Staircase tiles fitting work completed



March 2025



Block B1

RERA KM 15 OF 2022-2023

## Structural Work

- Foundation Work Completed
- Ground to 9<sup>th</sup> Floor Roof Slab Casted
- Lift Machine Room, Pergola, Head Room & Overhead Water Tank Casted

## Masonry Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor AAC Block Masonry Work Completed

## Plastering Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor Internal Plaster Completed
- Outside Plastering Work Completed

## Electrical Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor Electrical Pipe Concealed Work Completed
- 1<sup>st</sup> to 9<sup>th</sup> Floor Wiring & Switch sockets fitting completed

## Carpentry Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor Flush Door fitting work completed

## Plumbing Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor Bathroom Wall & Kitchen Pipe Concealed Work Completed
- 1<sup>st</sup> to 9<sup>th</sup> Floor Bathroom & Kitchen 4" Pipe Line Completed
- 1<sup>st</sup> to 9<sup>th</sup> Floor Bathroom & Kitchen CP Sanitary fittings work Completed

## Waterproof Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor Completed

## Putty & Paint Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor inside and outside putty Work completed
- B1 Tower External Paint Work completed

## Tiles Work

- 1<sup>st</sup> to 9<sup>th</sup> Floor tiles fitting Work Completed
- 1<sup>st</sup> to 9<sup>th</sup> Floor Kitchen slab granite fitting Work completed



March 2025



Block C1

RERA KM 15 OF 2022-2023

## Structural Work

- Foundation Work Completed
- Ground to 8<sup>th</sup> Floor Roof Slab Casted
- Lift Machine Room, Pergola, Head Room & Overhead Water Tank Casted

## Masonry Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor AAC Block Masonry Work Completed

## Plastering Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Internal Plaster Completed
- Outside Plastering Work Completed

## Electrical Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Electrical Pipe Concealed Work Completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Wiring & Switch sockets fitting completed

## Carpentry Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Flush Door fitting work completed

## Plumbing Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom Wall & Kitchen Pipe Concealed Work Completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Bathroom & Kitchen 4" Pipe Line Completed
- Bathroom & Kitchen CP Sanitary fittings work in progress

## Waterproof Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor Completed

## Putty & Paint Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor outside putty Work completed
- C1 Tower External Paint Work in Progress

## Tiles Work

- 1<sup>st</sup> to 8<sup>th</sup> Floor tiles fitting Work completed
- 1<sup>st</sup> to 8<sup>th</sup> Floor Kitchen slab granite fitting Work completed



March 2025



Club House

## Club House Work

- Structural Work Completed
- Masonry Work Completed
- Plastering Work Completed
- Electrical Pipe Concealed Work Completed
- Bathroom Wall & Kitchen Pipe Concealed Work Completed
- Waterproofing Work Completed
- Both External & Internal Putty Work Completed
- Bathroom Floors and Wall Tiles Fitting Work Completed
- Staircase Tiles Fitting Work Completed
- Carpentry Work In Progress